

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciaci, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 (R.A.) - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575 (R.A.)
Fax +39 02.90394441

export@sirsafety.com
www.sirsafety.com

COMPANY WITH
QUALITY SYSTEM
CERTIFIED
= ISO 9001 =

Name: Nitral Saldatore Ankle High Shoe	Code: 25007	Nitral Series
---	--------------------	----------------------


Description

Ankle boot, welder model, with 200 joule steel toecap and Zero Penetration composite midsole. Full grain leather upper. Velcro closure. PU and anti-heat nitrile rubber outsole. EVA SOFT 3 MM INSOLES, with anti-weariness properties; interchangeable, ensuring continued hygiene and cleanliness. DRY-PLUS polyester lining offering superb absorbing properties prevents feet overheating.

- Anti-cold lining
- Rubber overcap
- Lowered cleats section prevents accumulation of material
- Ergonomic heel angle
- Open angles to release accumulation of impurities
- Anti-slip outsole, wide contact surface with the ground to increase drainage of liquids
- Nitrile rubber oil and hydrocarbons resistant outsole
- Anti-slip ribbing
- Heel shape provides stability on ladder rungs

The product is designed and manufactured to comply with the essential health and safety requirements of Directive 89/686/EEC, and to conform to the requirements of European standards EN ISO 20345. It is classified as PPE Cat. II.



Category II	Colours Black - Orange	Available Sizes 39-46
Quantity/Carton 10	Important Information The footwear should be stored in a cool dry place, far from heat sources and direct light. Before each use, make sure that the footwear is in good condition. If the shoes are damaged, replace them.	Recommended for Light and heavy mechanical industry, Metallurgical Industry, Foundries, Chemicals, Oil & Gas Industry, Welding, Quarry, Mining Industry.
Dexterity	EC Standards EN ISO 20345  Safety Class:S3 HRO SRA	Storage and cleaning Clean the footwear with a soft brush and water.