



SAFETY SYSTEM[®]
WORKERS PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciai, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 (R.A.) - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575 (R.A.)
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com

COMPANY WITH
QUALITY SYSTEM
CERTIFIED
= ISO 9001 =

Name: Over Cap Saldatore	Code: 25066	MB21 CALZATURE SERIE OVERCAP
---------------------------------	--------------------	-------------------------------------

Description

Ankle high shoe, welder model, with 200 joule composite toecap and Zero Penetration composite midsole. Full grain leather upper, with Velcro closure.

PU FORCE dual density sole: High density polyurethane outsole with deep grooves offering excellent grip on uneven terrain.

Low density polyurethane insole, anti-weariness. Extra wide fitting shoe which provides a secure fit, whatever foot shape.

Anti-slip SRC standard.

DUAL FRESH Insoles in bi-component fabric with variable thickness and shock-absorbing properties. They are made from special foams and particularly contact-friendly fabrics which prevent perspiration.


3D-TEX LINING for foot ventilation, reducing perspiration.

Main features:

- High efficiency breathable lining
- Special protection with overcap
- Sharp-edged cleats to help the grip on wet floors
- Outsole with increased thickness
- Outsole with open angles deep grooves
- Outsole resistant to oils and hydrocarbons
- Anti-shock system
- Anti-slip ribbing
- Increased wide fitting suitable for any kind of foot

The product is designed and manufactured to comply with the essential health and safety requirements of Directive 89/686/EEC, and to conform to the requirements of European standards EN ISO 20345. It is classified as PPE Cat. II.



Category II	Colours Black	Available Sizes 38-47
Quantity/Carton 5	Important Information The footwear should be stored in a cool dry place, far from heat sources and direct light. Make sure footwear is in good condition, before use. If the shoes are damaged, replace them.	Recommended for Construction, Agricultural sector and Forestry, Light and heavy mechanical industry, Metallurgic industry, Handling and Logistics, Cleaners, Maintenance technicians and Installers.
Dexterity	EC Standards EN ISO 20345  Safety Class:S3 SRC	Storage and cleaning Clean the footwear with a soft brush and water.